

Training and Take the License



Training and Take the License



Training and Take the License



Training and Take the License



Training and Take the License

Training and Take the License

Model : QSPT TWT&E V2.0

Characteristic :

For prefabricated pipe, your company do not need a very experience technician for setting, you just need a trained person (welding control worker, pipe setting worker, arc welding worker, STT welding worker).

We can train the staff in a period one week or two weeks maximum.

Anyone can be trained.

Technical parameter:

Welding control worker: Train 2days, and get the license of welding control in 3 weeks.

Pipe setting worker: Train 3days, and get the license of welding control in 3 weeks.

Arc welding worker: Train 1 week, and get the license of welding control in 4 weeks.

STT welding worker: Train 1 week, and get the license of welding control in 4 weeks.